

Bluetooth firmware update.

Please download the attached bluetooth firmware file "[gocsdk 210](#)" and copy it to USB thumb drive or SD card, then update it as per the below pdf instructions. Then check if it is OK after the update.

Here is the video link:

<https://www.youtube.com/watch?v=c8CzJh9ThKE>

Link to download the file here:

<https://drive.google.com/file/d/1YEAJaoANhDxXvTwKRpsDFDTAKp7ZhN4I/view?usp=sharing>

PDF instructions:

https://www.sigmacarstereo.com/docs/Installation_instructions/BC6-5-0-bluetooth-update-instruction.pdf